

Case Study – FFP Assessment, Vessels.

ISSUE


- Under-Insulation Corrosion on High Pressure Separator
- Combined loading on vessel (pressure, pipework, walkways, etc.)

APPROACH

- Gather and review available data
- API579 Level 3 Assessment conducted

OUTCOME

- Separator shown to be fit-for-purpose
- Technical basis for scheduling future maintenance & repair.



An Overview of Current Best Practice in the Integrity Management of Offshore Facilities – A Case Study, R Jones Talisman Energy Limited, J Healy, A C Russell, M Dale, D Sandana, I Diggory, MACAW Engineering. Published at 5th Asian Pipeline Conference & Exhibition, Kota Kinabalu, Sabah. 28-29 October 2009